Release Notes for Ignite v10.4.1

Bug Fixes

[IGN-6770] If a Kframe switcher event is prepped with an effect, that effect will be taken to air even if a different effect is chosen from the Ignite Switcher GUI

- Ignite now respects the change of effect made in the Ignite switcher GUI after an event is prepped.

[IGN-6984] Chyron Hyper X - CG/SS Module does not recall graphics after importing a rundown

- CG/SS module for Chyron Hyper X now works properly after importing a rundown

[IGN-6988] IQ Template Manager (IQTM) may cause the values in a table to be set to default, and indicate an error state

- Ignite IQTM now takes care of missing values or rules in an IQT file, removing missing Values/Rules in a proper manner.

[IGN-6789] Timeline TMEs may appear overlapped after importing a rundown

- Ignite now eliminates a potential issue of TME overlapping after importing a rundown

[IGN-7126] 'Remove from Preview' can cause the SSL audio module to crash if the virtual source being removed is not configured in any audio pages

- 'Remove from Preview' now works properly when the relevant virtual source is not configured in an audio page

[IGN-7134] Server audio sources that are not in use are not taken off by AutoChannel

- AutoChannel now takes the audio sources that are not in use off

New Features

None